



Center Deck Drifts Down

Product: Groundsmaster® 4500/4700

Jan 25, 2012

Affected Units:

Models:

Serial Numbers:

Groundsmaster 4500

30857

290000001 and up

Groundsmaster 4700

30858

290000001 and up

Situation:

Important Information

In certain operating conditions (fast turns, bumpy terrain), the center deck may drift down after lifting it to “turn around height”. This undesired movement is due to the parallel design of the lift circuit hydraulics, which can allow independent deck movement.

Correction:

Toro has designed a Center Deck Lock Kit, which will not allow the center deck to move once it reaches “turn around height”. Install Deck Lock Kit (119-8633) to ensure the center cutting unit will not move once it has been lifted.

Contact your Toro Distributor should there be questions about this bulletin. Refer to TSB Rotaries # 08-36.

PRELIMINARY