



HoverPro Machine

Model No. 02600—Serial No. 314000001 and Up

Model No. 02602—Serial No. 314000001 and Up

Model No. 02603—Serial No. 314000001 and Up

Model No. 02604—Serial No. 314000001 and Up

Model No. 02606—Serial No. 314000001 and Up

Model No. 02609—Serial No. 314000001 and Up

Model No. 02611—Serial No. 314000001 and Up

Model No. 02615—Serial No. 314000001 and Up

Setup Instructions

Refer to the following chart for high idle specifications for your machine:

Model	Description	High Idle Specification
02600	HoverPro 400	4800 \pm 100
02602	HoverPro 450	3400 +0 / -150
02603	HoverPro 450	3400 +0 / -150
02604	HoverPro 500	3100 +0 / -150
02606	HoverPro 550	3100 +0 / -150
02609	HoverPro 450	3700 +0 / -150
02611	HoverPro 550	3700 +0 / -150
02615	HoverPro 550	4800 \pm 100

