



Importance of Drive Chain Maintenance

Product: Greens Pro 1200/1240

March 13, 2015

Affected Units:

Greens Pro 1200

Greens Pro 1200

Greens Pro 1200

Greens Pro 1240

Models:

44905

44906

44907

44912

Serial Numbers:

312000101-312999999

312000101-312999999

313000101-313999999

314000101-315999999

Situation:

Distributor field reports and customer feedback have indicated that early roller drive chain failures have occurred resulting in customer dissatisfaction. The customer must understand that the drive chain and sprockets are considered wear items. The customer has direct control over the life of these components by how they maintain these components.

The Greens Pro 1200 & 1240 Operators Manuals document specific process to follow to ensure full value of these drive components through daily lubrication and chain tension inspection.

Instructions: Refer to your Operator's Manual

- Before or immediately after daily use, the Pump Drive Cover must be removed to expose the chain drive assembly.
- **Inspect**. The chain tension must be inspected daily for the correct deflection as specified in the maintenance section of the Operators Manual. The tension inspection process is different for the Greens Pro 1200 (Fig. 1) and the Greens Pro 1240 . (Fig. 2)
- **Lubricate**. The Chain requires daily lubrication with a dry type lubricant. Toro recommends the use of Dri-Slide® Multi-Purpose Lubricant. (www.drislide.com)




Figure 1




Figure 2