

## Vehicles #04-10

Workman® GTX Gas-Rough Running Engine- Mandatory Rework

Product: Workman GTX Gas January 11, 2016

Affected Units: Models: Serial Numbers:

**GTX Gas** 07130 316000105-316000943

07130TC 316000101-316000224

Exempt Units: Model: Serial Numbers:

07130 316000531, 316000610,

316000831, 316000832, 316000835-316000835; 316000840-316000843;

316000848,

316000850-316000852; 316000854-316000857;

316000859

07130TC 316000221-316000223

## Copy of Notice to Owners Emissions Recall

Toro was recently informed by the Kohler engine manufacturer that your equipment may be emitting pollutants in excess of the Federal emission standards (and California standards) as defined in Title 40 of the Code of Federal Regulations. These emission standards were established to protect the public health or welfare from air pollution. In order to ensure your full protection under the emission warranty on your equipment by Federal law, and your right to participate in future recalls, we recommend that the equipment be serviced as soon as possible. Failure to do so could be legally determined as a lack of proper maintenance of an equipment. Failure to have this recall performed may cause the equipment to fail an emission inspection verification when such verifications are required under State or local law.

Toro Workman® GTX Gas off road utility vehicle affected by this Notice have the Kohler Gasoline engine manufactured between February 1, 2016 - August 8, 2016. The affected vehicles might be operating rough under certain load conditions.

This defect will be corrected with a carburetor and spark plug replacement.

Engine and vehicle performance, durability and operation are otherwise not affected by this modification.

This recall will be performed by authorized The Toro Company distributors. Please contact your authorized Toro distributor to schedule an appointment to have this recall performed. To locate an authorized distributor, search online at https://www.toro.com/en/locator.

The recall will take approximately 0.5 hours and will be performed at no charge to you. It is expected that repairs will begin December 2016.

If you no longer own the equipment, please return this notification to The Toro Company, 8111 Lyndale Avenue South, Bloomington, MN 55420-1196 with any information you can furnish that will assist us in locating the present owner.

If you have questions about this recall or have difficulty in obtaining repairs, please contact Toro's Warranty Department at 952-887-8697, Monday through Friday during normal business hours (8:00am-4:00pm CST).

We thank you for your business and sincerely apologize for any inconvenience this recall may cause in your business.