




MODEL NO. 30590-80001 & UP

PARTS
CATALOG


COLD STARTING KIT GROUNDMASTER® 580D



T-3034

KIT-COLD START

Ref. No.	Part No.	Description	No. Used	Ref. No.	Part No.	Description	No. Used
1	98-9014	Bracket-Injector	1	11	3290-378	Tie-Cable	1
2	3256-23	Washer-Flat	2	12	77-5010	Asm-Fuse	1
3	3253-4	Washer-Lock	2	13	77-5000	Switch-Temperature	1
4	33114-020	Screw-HH	2	14	43-2640	Tube-Fuel, Starting	1
5	77-2900	Asm-Valve	1	15	99-2309	Elbow	1
6	77-2910	Canister-Fluid, Starting	1	16	321-4	Screw-HH	4
7	2412-128	Clamp-Canister, Fuel	1	17	3296-42	Nut-Lock	4
8	77-2920	Nozzle	1	*	99-2337	Kit-Ether (Incl. Ref. #5-8 & 10-15)	1
9	98-9012	Tube-Cold Start	1				
10	77-2940	Gasket-Dirt	1				



T-3035

VALVE-CARTRIDGE ASM

Ref. No.	Part No.	Description	No. Used
†1		O-Ring	6
†2		O-Ring	6
†3		O-Ring	6
4	95-5636	Valve-Cartridge (Incl. Ref. #1-3)	3

Ref. No.	Part No.	Description	No. Used
*	95-5644	Kit-Cartridge Valve Seal (Incl. Ref. #1-3)	6

† Not serviced separately.

*Not Illustrated