



**Service Bulletin** 

**Commercial Products** 

July 25, 2019

## **Groundsmaster® Replacement Seats**

Bulletin Type	Information Only
---------------	------------------

Status Final Release

### Affected Units

Model	Model Number	Serial Number
Groundsmaster 4300-D	30854	315000001 to 315999999
Groundsmaster 4300-D	30864	313000001 to 403430000
Groundsmaster 4300-D	30864A	314000001 to 315999999
Groundsmaster 3500-D	30807	312000001 to 403440000
Groundsmaster 3500-G	30809	313000001 to 402700000
Groundsmaster 3500-D	30839/N	26000001 to 403440000
Groundsmaster 3505-D	30849	311000001 to 403450000

**Exempt Units** Not applicable

**Distribution** For Distributor and Customer Bulletin only

Attached Customer Bulletin may be copied to customers with affected product or instruct customers to access Service Bulletins at www.toro.com.

Situation Important Information

Toro has changed the seats for the Groundsmaster product lines and obsoleted the previous offering P/N 104-4620. This change requires a new seat assembly and base to be installed when a seat replacement is required.

#### **Corrective Action** Fix as Fail

Customers requiring a replacement seat on models and serial numbers listed will require a different seat assembly and base kits. Model and Serial Numbers outside the scope of this bulletin do not require any special action.

When a new seat configuration is ordered, the new seat assembly and base or attaching hardware must be ordered as shown in the table below.

Model Number	New Seat Kit Model/Part Number	Seat Mounting Plate
30854, 30864, 30864A, 30807, 30809, 30839/N, 30849	139-2700	138-6985-03

# Safety Follow reasonable and customary safety precautions. Awareness

- Parts Currently available
  - Refer to the table above.
- Parts Retention Not applicable
- **Required Tools** Not applicable
- Warranty Information only, not warrantable

Changes reflect continuous product improvements meeting customer expectations or special product applications. Conditions do not represent warrantable defects in materials or workmanship. Upgrades are made at the customer's request and expense.

- SRT Code Not applicable
- **References** Not applicable





**Customer Bulletin** 

**Commercial Products** 

July 25, 2019

## **Groundsmaster® Replacement Seats**

Status Final Release

Affected Units

Model	Model Number	Serial Number
Groundsmaster 4300-D	30854	315000001 to 315999999
Groundsmaster 4300-D	30864	313000001 to 403430000
Groundsmaster 4300-D	30864A	314000001 to 315999999
Groundsmaster 3500-D	30807	312000001 to 403440000
Groundsmaster 3500-G	30809	313000001 to 402700000
Groundsmaster 3500-D	30839/N	260000001 to 403440000
Groundsmaster 3505-D	30849	311000001 to 403450000

Situation Important Information

Toro has changed the seats for the Groundsmaster product lines and obsoleted the previous offering P/N 104-4620. This change requires a new seat assembly and base to be installed when a seat replacement is required.

Corrective Action Fix as Fail

Customers requiring a replacement seat on models and serial numbers listed will require a different seat assembly and base kits. Model and Serial Numbers outside the scope of this bulletin do not require any special action.

When a new seat configuration is ordered, the new seat assembly and base or attaching hardware must be ordered as shown in the table below.

Model Number	New Seat Kit Model/Part Number	Seat Mounting Plate
30854, 30864, 30864A, 30807, 30809, 30839/N, 30849	139-2700	138-6985-03