



Customer Bulletin

Commercial Products

January 14, 2021

Sand Pro Seat Replacements

Sand Pro® 3040 and 5040

Bulletin Type Information Only

Status Final Release

Affected Units

| Model Numbers | Serial Numbers |
|---------------|------------------------|
| 08703 | 260000001 to 407599999 |
| 08705 | 260000001 to 407599999 |
| 08884 | All |
| 08887 | All |

Situation Important Information

Sand Pro seats on affected machines with models and serial numbers listed above have been obsoleted and replaced with seat kits.

Corrective Action

Fix as Fail

See the table below for correct seat kits required for specific Sand Pro model and serial numbers.

| Model Numbers | Required Kit |
|---------------|-------------------|
| 08703 | Seat Kit 144-1380 |
| 08705 | Seat Kit 144-1380 |
| 08884 | Seat Kit 144-7056 |
| 08887 | Seat Kit 144-7056 |

Safety Awareness Follow reasonable and customary safety precautions.

Parts Currently available

Note: Seat Kit 144-7056 will be available Spring 2021.

Warranty Information only, not warrantable

References Find the latest operator's manuals, service manuals, schematics, parts catalogs, and customer bulletins at www.Toro.com.