

# 44in Outer Spindle Assembly Replacement Kit

**Mid-Size Mowers** 

Model No. 106-0803

### **Parts Catalog**

#### **Ordering Replacement Parts**

To order replacement parts, please supply: the part number, the quantity, and the description of each part desired.

#### **Understanding Reference Numbers**

Each identified part in an illustration has a reference number. The reference number for a part also appears in the parts list, along with other information about the part.

This catalog uses two special reference number formats, one to indicate parts in a service assembly and another to indicate the quantity of a given part in an illustration.

#### Service Assembly Reference Numbers

Parts in service assemblies have reference numbers in the form **a:b**. The **a** represents the reference number of the entire service assembly and the **b** represents a sequential number unique to each part within the service assembly.


For example, a wheel assembly might be identified by reference number **6**, the tire by **6:1**, the valve by **6:2**, and the wheel by **6:3**. When you order the assembly identified by reference number 6, you receive all parts identified by reference numbers 6:1, 6:2, and 6:3. However, you may also order any part individually.

Reference numbers of this type appear in illustrations and in part lists.

#### **Reference Numbers Indicating Quantity**

In an illustration, if a reference number indicates more than one part, the reference number has the form  $\mathbf{nX}$   $\mathbf{y}$ . The  $\mathbf{n}$  represents the quantity of the part, the  $\mathbf{X}$  is the multiplication symbol, and the  $\mathbf{y}$  represents the reference number.

For example, in an illustration, the reference number **2X 37** means that two of the parts identified by reference number 37 are indicated.



Sheet No.:0

## Spindle Assembly

Ref. No.	Part No.	Qty.	Description
1 2 3 4 5 6 7 8	3219–7 7–4150 104–1181 106–0873 104–6325 106–0818 106–0794 106–0780	1 1 1 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Nut-Hex Washer Pulley ASM Shield-Bearing Bearing Housing-Spindle Spacer-Bearing Shaft-Spindle

Ref. No.	Part No.	Qty.	Description