




MODEL NO. 30589	PARTS CATALOG
COLD STARTING KIT GROUNDMASTER 580D	



T-1142-1

KIT-COLD START

Ref. No.	Part No.	Description	No. Used
1	3296-42	Nut-Lock	8
2	77-2930	Bracket-Injector	1
3	321-4	Screw-HH	8
4	77-2900	Asm-Valve	1
5	77-2910	Canister-Fluid, Starting	1
6	2412-128	Clamp-Canister, Fuel	1
7	77-2920	Nozzle	1

Ref. No.	Part No.	Description	No. Used
8	77-2890	Tube-Cold Start	1
9	77-5010	Asm-Fuse	1
10	3290-378	Tie-Cable	1
12	77-5000	Switch-Temperature	1
13	43-2640	Tube-Fuel, Starting	1
14	77-2950	Elbow	1