




PART NO. 93-9250

PARTS
CATALOG**CE UPDATE KIT**

264-6E Lawn & Garden Tractor Model No. 72062

INTERNATIONAL PARTS REFERENCE
EUROPEAN PARTS KIT NO. 93-9250


DESCRIPTION	LOCATION	ENGLISH PART NO.	EUROPEAN PART NO.	QTY.
Decal Battery Charge In- structions	Top Of Battery		93-6668	1
Decal Danger	Front of Battery		93-7276	1
Decal Dash	On Dash	92-7087	93-7255	1
Decal Dash	On Dash	92-7086	93-7256	1
Decal Danger	On Back of Hoodstand	92-7089	93-7312	1
Decal Danger	Footrest Plate	92-8946	93-7314	1
Decal Lift Int'l	On Lift Lever	92-7085	93-7323	1
Decal Installation Belt	On Side of Frame	79-7020	93-7324	2
Decal Oil Check	Over Fuel Cap	83-4690	93-7328	1
Decal CE 264HE	Fender by Serial Plate		94-1450	1



BATTERY ASSEMBLY

Ref. No.	Part No.	Description	No. Used
1	93-6668	Decal – Battery Charge Instructions	1


Ref. No.	Part No.	Description	No. Used
2	93-7276	Decal – Danger	1



LIFT ASSEMBLY

Ref. No.	Part No.	Description	No. Used
1	93-7323	Decal - Lift Int'l	1


Ref. No.	Part No.	Description	No. Used



BELT INSTALLATION ASSEMBLY

Ref. No.	Part No.	Description	No. Used
1	93-7324	Decal - Belt Installation	2


Ref. No.	Part No.	Description	No. Used



HOODSTAND ASSEMBLY

Ref. No.	Part No.	Description	No. Used
1	93-7312	Decal – Slope/Park Brake	1

Ref. No.	Part No.	Description	No. Used



FOOTREST PLATE ASSEMBLY

Ref. No.	Part No.	Description	No. Used
1	93-7314	Decal - Danger	1

Ref. No.	Part No.	Description	No. Used

In an effort to make improvements available to TORO owners as quickly as possible, minor changes are incorporated into Toro's products from time to time that do not become immediately shown in the Parts Catalog. If such a change has been made in your unit, which is not reflected in your manual, see your TORO Distributor or his Authorized TORO Service Dealer for information and part numbers.

COUNTRIES OTHER THAN THE UNITED STATES OR CANADA

service or have difficulty obtaining guarantee information, contact the TORO importer. If all other remedies fail, you may contact us at The Toro Company.

MAINTENANCE RECORD

[illegible]