




PART NO. 93-9256

PARTS
CATALOG**CE UPDATE KIT**

48" Side Discharge Cutting Unit Model No. 78260

INTERNATIONAL PARTS REFERENCE
EUROPEAN PARTS KIT NO. 93-9256


DESCRIPTION	LOCATION	ENGLISH PART NO.	EUROPEAN PART NO.	QTY.
Decal Wheel Adjustment	Front Side of Deck Assembly	68-3380	93-7282	2
Decal Danger	Top of Chute Assembly	93-1122	93-7316	1
Decal Danger	Top of Deck Assembly	92-7108	93-7317	2
Decal Belt Installation	Top of Deck Assembly	116286	93-9285	1
Front Shield Assembly	Front of Deck		93-0542	1
Hex Head Screw	Front Shield Ass'y		911445	4
Hex Jam Nut	Front Shield Ass'y		3218-3	4



DECK ASSEMBLY

Ref. No.	Part No.	Description	No. Used
1	93-7282	Decal - Wheel Adjustment	2
2	93-7317	Decal - Danger	2
3	93-9285	Decal - Belt Installation	1

Ref. No.	Part No.	Description	No. Used
4	93-0542	Shield - Front	1
5	911445	Screw - Hex Hd.	4
6	3218-3	Nut - Hex Jam	4



CHUTE ASSEMBLY

Ref. No.	Part No.	Description	No. Used
1	93-7316	Decal - Danger	1

Ref. No.	Part No.	Description	No. Used

PRODUCT CHANGES

In an effort to make improvements available to TORO owners as quickly as possible, minor changes are incorporated into Toro's products from time to time that do not become immediately shown in the Parts Catalog. If such a change has been made in your unit, which is not reflected in your manual, see your TORO Distributor or his Authorized TORO Service Dealer for information and part numbers.

COUNTRIES OTHER THAN THE UNITED STATES OR CANADA

Customers who have purchased TORO products exported from the United States or Canada should contact their Toro Distributor (Dealer) to obtain guarantee policies for your country, province or state. If for any reason you are dissatisfied with your Distributor's

service or have difficulty obtaining guarantee information, contact the TORO importer. If all other remedies fail, you may contact us at The Toro Company.

MAINTENANCE RECORD

[illegible]